



T-Multi Switch



Roca


A5A704A

2 WAYS




A5E704AC00

(mm)




A5A714A

2 WAYS




A5E714AC00




A5A724A

3 WAYS




A5E724AC00

(mm)




A5A734A

3 WAYS



A5E734AC00





P

bar



10 Max



T

°C



80 Max



65
50



Q

(3 bar)

L/min

WAY

①

22

WAY

②

21



6,5

WAY

③


14




6,5




A5A704A




A5E724A



A5E714A



x1




x1



x1

A5E734A



x1




x1




x1




1




2





3





4



5



6



L= 13-15 A


L= 16-19 B

L= 20-23 C



L= 24-26 A+D

L= 27-30 B+D

L= 30-33 C+D





7





Use only
with joint D



8




9




10


⚠ Remove the burrs




11




12




13




14




15




16




17




18



19





20







1



Use only
with joint D



2




3




⚠ Max. 0,4 N/m


4





5




6




7



8





9



10

REPLACE THE FLEX HOSE
AND START FROM POINT 18






A5A704A

1
2


3




A5A714A

1
2


3



A5A724A



A5A734A



1	AG02799..R	
2	AG02779..R	
3	AG02786..R	
4	A5B9B61..0	1.5 mt

5	AG02782..R
6	AG02787..R
7	AG0279800R

CÓDIGO / CODE

0000000 . 0

ACABADO / FINISH

→www.roca.com

